



Production Discontinuation of MELIPC MI1000 Series

■Date of Issue

December 2022

■Relevant Models

MI1002-W, MI1002-W-CL

Thank you for your continued support of Mitsubishi Electric industrial PC, MELIPC series.

We announce that MELIPC MI1000 series will be discontinued, as explained below.

1 MODEL TO BE DISCONTINUED

Series	Model
MELIPC MI1000 series	MI1002-W, MI1002-W-CL

2 SCHEDULE

- Transition to made-to-order: December 28, 2022
- Order acceptance: Through June 30, 2023
- Production discontinuation: July 31, 2023

3 REASONS FOR DISCONTINUING PRODUCTION

Some parts of the above products are now obsolete, and we will have difficulty to maintain our production system.

4 REPAIR ACCEPTANCE

- Repair support period: Until July 31, 2028 (for five years after the discontinuation of production)

This is because this product is developed and manufactured by Mitsubishi Electric Corporation in collaboration with NEC Corporation.

Thank you for your understanding in advance.

5 ALTERNATIVE MODEL

There is no alternative model available.

When replacing the products with a new one, please consider purchasing an industrial PC on the market.

For the specifications of this product, refer to the following:

 MI1002-W User's Manual

Industrial PCs on the market

The following table shows industrial PCs on the market for replacement.

Note that Mitsubishi Electric does not conduct verification of the product. Before using it, be sure to confirm that no operational problem will occur in a system. In addition, use the product according to the specifications (standards).

Model to be discontinued	Alternative model		
Model	Manufacturer	Model	Reference
MI1002-W	Advantech Co., Ltd.	UNO-137	www.advantech.com
MI1002-W-CL	Contec Co., Ltd.	BX-T210	www.contec.com

For the production status of each product above, contact its manufacturer.

REVISIONS

Version	Date of Issue	Revision
A	December 2022	First edition

TRADEMARKS

The company names, system names and product names mentioned in this bulletin are either registered trademarks or trademarks of their respective companies.

In some cases, trademark symbols such as [™] or [®] are not specified in this bulletin.